From: Tim Davis/=TMS/Toyota. Sent:2/12/2009:11:00 AM.

To: [-] Gary Heine/=TMS/Toyota@Toyota.

Cc: [-] Daisuke Sakakibara/=TMS/Toyota@Toyota;Mike Robinson/=Mobile/Toyota@Toyota

Bcc: [-]

Subject: Re: Fw: BuzzAlert: 2007 Camry V6 owner reports "Bank 1 VVTi" Oil Line leak, tells Camry owners "beware".

I was able to find 11 vehicles that have been bought back or are going to be bought back for VVT-i oil pipe related issues.

Tim Davis Product Engineer Quality Assurance - Powertrain Toyota Motor Sales, U.S.A., Inc. Phone: 310.468.6692

Fax: 310.974.5779

Gary Heine/TMS/Toyota 02/10/2009 08:15 AM

To Daisuke Sakakibara/TMS/Toyota@Toyota

cc Tim Davis/TMS/Toyota, Mike Robinson/Mobile/Toyota@Toyota

Subject Fw: BuzzAlert: 2007 Camry V6 owner reports "Bank 1 VVTi" Oil Line leak, tells Camry owners "beware"

You might want to consider sharing with TMC. We are looking into buybacks but the data is muddy

Regards, Gary Heine

Quality Assurance Powertrain Manager

Toyota Customer Services Division

O-310 468 2521

C-310 977 0860

F-310 381 7783

----- Forwarded by Gary Heine/TMS/Toyota on 02/10/2009 08:06 AM -----

"Colacurcio, Joe" < Joe. Colacurcio@nielsen.com>

02/10/2009 07:59 AM

To <Gary_Heine@Toyota.com>, <mike_robinson@toyota.com>, <greg_bryan@toyota.com>,

<gordon rush@toyota.com>

cc <Jeff_Northrup@Toyota.com>, "Stephenson, Bill" <Bill.Stephenson@nielsen.com>, "Hamm, Scott"

<Scott.Hamm@nielsen.com>

Subject BuzzAlert: 2007 Camry V6 owner reports "Bank 1 VVTi" Oil Line leak, tells Camry owners "beware"

Good morning.

Please note that on February 7, 2009, a new discussion thread was initiated on ToyotaNation.com regarding an owner-experienced problem associated with the 2GR 3.5L V6 and the "Bank 1 VVTi Oil Line Leaking Issue." The owner reports that after not having paid significant attention to his wife's 2007 Camry XLE V6 over the past 10,000 miles, he noticed a pool of oil under the Camry in the driveway. After taking the vehicle to the dealership, it was determined that the leak was coming from the Bank 1 VTTi Oil Line. The owner states that in his research, this may be a commonly occurring problem regarding 2GR V6s that have 45,000-65,000 miles on the odometer, and warns

other Camry owners to "beware". There are about 20 messages in response, though many are non-owners.

Original post:

"Well Apparently Toyota has not corrected the issue wit hthe 2GR and the Bank 1 VVTi Oil Line Leaking Issue. Ever since I got my 07 TI Type-S my wife has been driving the camry... so I haven't really driven it much for the last 10k or so! ... lon story short ... last week I noticed a pool of oil under the camry in my driveway. I checked the dipstick, and to my surprise, the stick was DRY!!!

I added some oil (5 qts to be exact!!!) and took the car to the dealer immediately. It appears that the leak was comming from the Bank 1 VVti Oil Line. My camry has 51k on it now, and thank god this was covered under the 60k powertrain factory warranty or I would have been pissed!

Just BEWARE ... keep an eye on your V6 camrys fellas ... since the TSB was issues on the 05 Avalon in November 2005 ... this has been an ongoing issue that Toyota has apparently been keeping hush hush! It seems to be happening from my research on vehicles with the 2GR between 45k to 65k miles ... check the rubber hose going to Bank 1 VVTi Oil Line ... where the metal line meets the rubber hose apparently the metal clamp wears through the rubber hose over time this friction causes a pinhole in the rubber line (in my case a much larger hole) causing you to loose a significant amount of oil. ... if not caught in time ... have fun trying to get that repaired under warranty!!!"

February 7, 2009 by PillPusher84 on ToyotaNation.com

http://www.toyotanation.com/forum/showthread.php?t=285250

Regards, Joe Colacurcio Senior Analyst, Automotive Nielsen Online

The Nielsen Company 50 West RiverCenter Blvd. Third Floor Covington, KY 41011

859.905.4936 voice 610.462.3048 mobile joe.colacurcio@nielsen.com www.nielsen-online.com http://nielsen-online.com/blog